

Technický list produktu (datasheet): HSELDA40WP

FTTH zás pro mont na zed', š80 x v28 x h80 mm, prázdn. pro 4vl.

RAL9010, vhodná i pro montáž na DIN lištu



SCHRACK-Info

FTTH empty outlets serve as a universal interface for fiber optic installations.

They offer a high degree of flexibility when it comes to equipping and adapting the network infrastructure.

Empty outlets are an ideal solution for organizing the fiber-optic connection efficiently and ensuring a clean, well-structured installation—especially when planning for future expansions or upgrades of the network structure.

Features

- Fiber Optic In-House-Cabling
- Offers connection options for up to 4 end devices
- The box is suitable for pre-assembled cables or for pigtails

- Flexible cable entry options
- Lid locks into place
- 2 screws, 2 dowels, and 2 shrink splice protectors included

Optional Accessories

Couplers:

- HSELSK09MR
- HSELSK09GR

Pigtails:

- HLP09M041P
- HLP09D041P

Safety information:

Avoid direct contact with light sources:

- Fiber optic cables—especially those with active light sources such as lasers (e.g., in optical communication systems)—can emit hazardous radiation that may damage the eyes.
- Never look directly into the light of a fiber optic cable, even if the light source is invisible to the naked eye.

Wear protective eyewear:

- When working with fiber optic cables, especially during tests or when using lasers, always wear safety glasses to protect your eyes from harmful radiation.

Handle cables correctly:

- Plug in and unplug cables only by holding the connector, and never pull directly on the cable.

Do not bend or crush:

- Fiber optic cables are sensitive to mechanical stress.

Protect from damage:

- Install cables in dedicated conduits or use protective materials to prevent physical damage.

Keep connectors clean:

- Fiber optic connectors must be free of dust and dirt.
- Even small particles on the connectors can significantly reduce signal quality.

Observe temperature limits:

- Do not expose cables to extremely high or low temperatures.
- Follow the manufacturer's specifications for the cable's maximum operating temperature.


Inspect regularly:

- Frequently check cables for visible damage such as cracks, bends, or signs of wear.
- Damaged cables must be replaced immediately.

Technické informace

Šířka (netto) (mm)	80,00
Výška (netto) (mm)	28,00
Hmotnost (netto) (kg)	0,05
Barva	RAL 9010 (čistá bílá)
Minimální teplota okolí (°C)	-40
Maximální teplota okolí (°C)	75

**Rozměrový výkres: FTTH zás pro mont na zed', š80 x v28 x h80 mm,prázd.
pro 4vl.**



Tabulka objednacích čísel

POPIS	OBJ. ČÍSLO
FTTH zás pro mont na zed', š80 x v28 x h80 mm,prázdn. pro 4vl. RAL9010, vhodná i pro montáž na DIN lištu	HSELDA40WP
Volitelné příslušenství	
FFTH FO spojka LC/APC-Duplex, plast, OS2, keramika krytka proti prachu, CLASSIC	HSELSK09MR
FFTH FO spojka SC/APC-Simplex, plast, OS2, keramika krytka proti prachu, CLASSIC	HSELSK09GR
Pigtail LC/APC 9/125um OS2, Clas, Easy Strip, délka 1m, 4ks Easy Strip, colored according to IEC 60304, CLASSIC	HLP09M041P
Pigtail SC/APC 9/125um OS2, Clas, Easy Strip, délka 1m, 4ks Easy Strip, colored according to IEC 60304, CLASSIC	HLP09D041P
Čisticí nástroj pro optické vlákna LC a MU Vhodné pro konektory UPC a APC. Více než 1 000 čisticích cyklů.	HSELSZT001
Čisticí nástroj pro optické vlákna SC, ST, FC a E2000 Vhodné pro konektory UPC a APC. Více než 1 000 čisticích cyklů.	HSELSZT002
Měřič výkonu FO s integr. laserovým zdrojem světla (VFL) Možnost testování měděného kabelu s konektorem RJ45. POZOR: Jedná se o produkt laserové třídy 2. Nedívejte se přímo do paprsku. Pokud zařízení nepoužíváte, vždy nechte kryt portu VFL nasazený. Při práci s optickými systémy se doporučuje používat ochranné brýle proti laserovému záření.	HSELSZT003